



1994 GMC Pickup K1500

Fig. 1: Identifying Steering Column Switches
Courtesy of GENERAL MOTORS CORP.




© 2008 Mitchell Repair Information Co., LLC.


1994 GMC Pickup K1500-Fig. 62: Exterior Lamps Circuit




1994 GMC Pickup K1500-Fig. 69: Headlamps Circuit, W/ Sealed Beam Lamps




1994 GMC Pickup K1500-Fig. 71: Horn Circuit




1994 GMC Pickup K1500-Fig. 82: Power Distribution Circuit, Gasoline (1 of 4)




1994 GMC Pickup K1500-Fig. 82: Power Distribution Circuit, Gasoline (1 of 4)



1994 GMC Pickup K1500-Fig. 74: Courtesy Lamp Circuit



1994 GMC Pickup K1500-Fig. 130: Warning System Circuits



1994 GMC Pickup K1500-Fig. 131: Front Washer/Wiper Circuit

